0018

From:

Karl Houskeeper

To:

kit@emerytelcom.net

CC:

Angela Nance; Daron Haddock; Suzanne Steab

Date:

11/10/2009 3:40 PM

Subject:

October 2009 Inspection Report

Attachments: Horizon October 2009.pdf

Kit,

Attached is the October 2009 inspection report for Horizon.

Karl

Owtgring CO070020



State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director Permitee: HIDDEN SPLENDOR RESOURCES INC

Operator: HIDDEN SPLENDOR RESOURCES INC Site: HORIZON MINE

Address: 3266 S 125 W, PRICE UT 84501 County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:

Company Kit Pappas Manager of Environmental/Engineering Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0070020			
Inspection Type:	PARTIAL			
Inspection Date:	Thursday, October 22, 2009			
Start Date/Time:	10/22/2009 9:30:00 AM			
End Date/Time:	10/22/2009 12:30:00 PM			
Last Inspection:	Thursday, September 24, 2009			

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 55 Deg. F. InspectionID Report Number: 2184

Accepted by: jhelfric

11/10/2009

Current	Acreages

Total Permitted		
Total Disturbed		
Phase I		
Phase II		
Phase III		

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground ☐ State ☐ Surface ☐ Loadout ☐ County Processing ☐ Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

inspector's	Signature:
-------------	------------

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov Date

Thursday, October 22, 2009

Permit Number: C0070020 Inspection Type: PARTIAL

Inspection Date: Thursday, October 22, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		V	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	V		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	V		V	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit	. 🗆			
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070020 Inspection Type: PARTIAL

Inspection Date: Thursday, October 22, 2009

Inspection Continuation Sheet

Page 3 of 3

2. Signs and Markers

The mine ID sign was observed at the point of public access to the mine. The sign contained the name of the mine, address, phone number, permit number, and MSHA number.

4.a Hydrologic Balance: Diversions

Several tumble weeds are in the diversions. The weeds need to be removed to prevent them from plugging the culvert inlets.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment pond is being cleaned. The pond needs to be cleaned before adverse conditions set in.

8. Noncoal Waste

Several items of noncoal waste need to be gathered up and placed back in appropriate storage facility. Trash was being hauled and the windy conditions were spreading the noncoal items around the site.